

ACQUISITION MILESTONE

<p>CONCEPT STUDIES</p> <p>AoA TEMP</p>
--

<p>SYSTEM DEVELOPMENT AND DEMONSTRATION</p> <p>AoA APB ICEME LCCE ORD STAR TEMP</p>

<p>PRODUCTION OR PROCUREMENT</p> <p>APB ICEME ORD STAR</p>
--

DEPOT MAINTENANCE PLANNING DURING ACQUISITION

	A	B	C
ACQUISITION PHASE	CONCEPT AND TECHNOLOGY DEVELOPMENT PHASE	SYSTEM DEVELOPMENT AND DEMONSTRATION PHASE	PRODUCTION AND DEPLOYMENT PHASE

MAINTENANCE PLANNING

<ul style="list-style-type: none"> • DEFINE BASELINE MAINTENANCE CONCEPT • ADVISE PROGRAM MANAGER FOR DEPOT MAINTENANCE (PMDM), SEA 04L12 POTENTIAL FOR NEW START • IDENTIFY POC IN PROGRAM OFFICE 	<ul style="list-style-type: none"> • PREPARE DETAILED MAINTENANCE PLAN • VALIDATE DEPOT LEVEL MAINTENANCE REQUIREMENTS • PREPARE DECISION TREE ANALYSIS (DTA) • SUBMIT JLC FORMS 27 AND 44 • INERIM DEPOT SUPPORT (IDS) REQD? IF SO PREPARE TENTATIVE TO PERMANENT DOP PLAN • SUBMIT JLC FORMS 28 – 51 (AS REQUIRED) • SOURCE OF DL REPAIR DECISION RECEIVED 	<ul style="list-style-type: none"> • EFFECT ADJUSTMENTS TO MAINTENANCE PLAN AS NECESSARY • INITIATE IDS TO SUPPORT TECHEVAL, OPEVAL AND FOLLOW-ON SUPPORT AS NECESSARY • TRANSITION FROM INTERIM TO PERMANENT DOP • CERTIFY PERMANENT DOP
<p>MISSION NEED STATEMENT (MNS) OR PROGRAM DECISION MEMORANDUM (PDM)</p>	<p>PROGRAM OBJECTIVES MEMORANDUM (POM) UPDATE</p>	<p>POM UPDATE</p>

FUNDING

ATTACHMENT 1 CHAPTER 2